

CONFIDENTIAL

[illegible]

[illegible]

1 EXAMPLE OF REV SYMBOL

2 EXAMPLE OF ITEM BALLOON

3 EXAMPLE OF NOTE CALLOUT

C.00 EXAMPLE OF WIRE TAIL EXIT TO RIGHT FROM FACE VIEW OF CONNECTOR

#### NOTES:

1. PERFORM SPLICES FOR C.01 AND C.02 IN THIS STRAIGHT REGION
2. ANY LEG LESS THAN 110mm SHALL NOT HAVE SLEEVE APPLIED
3. ALL SLEEVED LEGS SHALL MAINTAIN MINIMUM 50mm WIRE BREAKOUT LENGTH WITH NO SLEEVE
4. ANY FINAL OUTER WRAP OF TAPE MUST BE SECURED WITH A ZIP TIE. WRAP LEGS SUCH THAT AS MANY TAPE ENDS AS POSSIBLE ARE COLLECTED UNDER EACH TRANSITION TO MINIMIZE ZIP TIES NEEDED. DO NOT INSTALL A ZIP TIE WHEN A TAPE END HAS BEEN WRAPPED OVER BY SPIRALING TAPE. THE INTENTION OF THIS NOTE IS TO SECURE ANY "END" OF TAPE THAT IS NOT RESTRAINED.
5. DO NOT APPLY PVC TUBE TO THIS LEG; ONLY TAPE
6. SLEEVE UP TO RING TERMINAL
7. APPLY SERVICE LOOPS TO CONNECTOR. LENGTH INCL. LOOPS
8. APPLY LABEL UPON TRANSITION, NOT WIRE BREAKOUT
9. DO NOT APPLY SLEEVE OR TAPE
10. INSTALL FERRITE AS CLOSE TO 90 DEG TURN AS POSSIBLE. FIX TO WIRES WITH HEATSHRINK AS SPECCED

